LABORATORY EQUIPMENT OVERVIEW

ERTC/IRWA TRAINING 2023-2024



TODAY'S AGENDA

| TYPE | INSTRUMENT |
|--------------------|--|
| Colorimeters | Pocket Colorimeter II – DR300 – DR900 – SL1000 – CL-17 |
| Probes | pH/ISE |
| Spectrophotometers | DR3900 |
| Turbidimeters | 2100P - 2100Q - TU5200 - TU5300 |

Explanation - Testing - Calibration - Maintenance



PORTABLE COLORIMETERS

- > Types of Colorimeters
 - Pocket Colorimeter II Single Analyte
 - DR300 Single Analyte
 - DR900 Multiple Analytes
 - SL1000 Multiple Analytes (Simultaneously)
 - CL-17 Online Single Analyte (Chlorine)



POCKET COLORIMETER II and DR300

Chlorine, MR/HR

Ozone

Molybdenum, LR/HR

Phosphate

Chlorine, pH

Zinc

➤ Most Common Analytes

- Free and Total Chlorine
- Iron and Manganese
- Phosphate
- NAP (Total Ammonia, Monochloramine, Free Ammonia, and Nitrate)

DR300 Pocket Colorimeter, Chlorine & pH, with Box Product Number: LPV445.97.12110 Ships within 6-8 weeks Parameter Aluminum Ammonia Nitrogen Bromine Chlorine dioxide Chlorine, LR/HR

Iron, Ferrover

Monochloramine/Free Ammonium

Iron, TPTZ

Nitrate

Manganese, HR

Oxygen, dissolved



TOTAL CHLORINE OPTIONS

- ➤ Free or Total Chlorine (Low Range LR)
 - Range = 0.02 mg/L 2.00 mg/L
 - 10 mL sample (1) 10 mL reagent pack 25 mm sample cell
- > Free or Total Chlorine (Mid Range MR)
 - Range = 0.05 mg/L 4.00 mg/L
 - 10 mL sample (1) 25 mL reagent pack 25 mm sample cell
- ➤ Free or Total Chlorine (High Range HR)
 - Range = 0.1 mg/L 8.0 mg/L
 - 5 mL sample (2) 10 mL reagent packs 1 cm sample cell
- >Analysis Time
 - Free chlorine within 1 minute
 - Total chlorine 3-6 minutes



PORTABLE COLORIMETERS

▶ Calibration

Initial Factory Calibration – No other calibration recommended

>Spec Checks

- Secondary Standards
- Liquid Standards
- Out of Spec Return for Factory Calibration Reset





PORTABLE COLORIMETERS

> Spec Check Options

- DPD Chlorine LR
- DPD Chlorine MR
- DPD Chlorine HR
- Fluoride
- Monochloramine & Free Ammonia
- Ozone





DR900

Benefits

- Ability to read at different wavelengths
- Ability to read multiple analytes










SL1000 Chem Keys






SL1000 Chem Keys





SL1000





SL1000









SL1000




-






Breakpoint Chlorination Curve





SL1000 Results



ONLINE COLORIMETERS (CL-17)





ONLINE COLORIMETERS (CL-17)

Section 6 Calibration and adjustment

The calibration curve of the analyzer is set at the factory for performance to specifications. Calibration can be done for performance verification.

No user adjustments to the factory calibration curve are recommended unless required by a regulatory agency for compliance reporting purposes, or a large repair of the analyzer is done.

7.1 Maintenance schedule

Table 6 shows the recommended schedule of maintenance tasks. Facility requirements and operating conditions may increase the frequency of some tasks.


Table 6 Maintenance schedule

| Task | 1 month | 6 months | As necessary |
|--|----------------|----------|--------------|
| Clean the cell on page 20 | X ² | | |
| Replace the reagent bottles on page 21 | Х | | |
| Replace the stir bar and tubing harness ³ | | x | |
| Clean the screen in the Y-strainer on page 22 | | | X |



рН

pH SCALE





pН

| | pH | H+ Activity | OH- activity |
|---------|----|--------------------------|-----------------|
| | 0 | 1.E+00 1 | 0.0000000000001 |
| | 1 | 1.E-01 0.1 | 0.000000000001 |
| | 2 | 1.E-02 0.01 | 0.00000000001 |
| acid | 3 | 1.E-03 0.001 | 0.0000000001 |
| | 4 | 1.E-04 0.0001 | 0.0000000001 |
| | 5 | 1.E-05 0.00001 | 0.000000001 |
| | 6 | 1.E-06 0.000001 | 0.00000001 |
| neutral | 7 | 1.E-07 0.0000001 | 0.0000001 |
| | 8 | 1.E-08 0.00000001 | 0.000001 |
| | 9 | 1.E-09 0.000000001 | 0.00001 |
| | 10 | 1.E-10 0.0000000001 | 0.0001 |
| base | 11 | 1.E-11 0.00000000001 | 0.001 |
| | 12 | 1.E-12 0.000000000001 | 0.01 |
| | 13 | 1.E-13 0.0000000000001 | 0.1 |
| | 14 | 1.E-14 0.000000000000001 | 1 |



pH Probe Conditioning

→ Conditioning

- pH electrodes are shipped with the electrodes moist.
- Before first use, use the steps below to condition.

▶ Conditioning Steps

- Remove the cap or rubber boot and rinse with distilled or deionized water.
- Place the electrode in one of the below liquids for 20 minutes:
 - 3.8M or 4.0M KCl
 - 4.0 pH Buffer
 - 7.0 pH Buffer
- Rinse the electrode in distilled or deionized water. Ready for use.



pH Slope Calibration


- ➤ What is a pH slope?
 - The linear correlation between raw voltage and a pH value
- >Theoretical Slope
 - At pH 7, the theoretical mV value should be 0 mV.
 - The theoretical slope is 59.16 mV at 25 degrees C.
 - So 1 pH unit lower = 59.16 and 1 pH unit higher = 59.16
- **▶** Calibration
 - Recommend at least a two-point slope.
 - 7.0 pH buffer should be one of the points.



pH Probe Calibration Results

The ideal pH range for slope is 95% to 105%. However, a pH slope between 85% and 105% is also acceptable. If the pH slope is outside this range, it may be an indication that your pH probe needs replacing. Therefore, the pH slope range varies depending on how well your pH probe is working properly. Mar 14, 2023








SOUTHERN ILLINOIS UNIVERSITY EDWARDSVILLE

-2



















pH Probe Care

→ Handling

- Rinse with distilled or deionize water between samples.
- Never wipe probe. Static charges cause erroneous readings.

> Filling Solution

- Fill up to the refill hole.
- Leave refill hole open when measuring to ensure flow.

≻Storage

- Always keep moist.
- Store in 4M KCl, 4.0 pH buffer, or 7.0 pH buffer. Not DI or distilled.



Nitrate Probe



Section 10 Consumables

Note: Product and Article numbers may vary for some selling regions. Contact the appropriate distributor or refer to the company website for contact information.

| Description | Quantity | Item no. |
|---|----------|----------|
| Nitrate Ionic Strength Adjustor Powder Pillows (buffer only) | 100/pkg | 2984799 |
| Nitrate Ionic Strength Adjustor Powder Pillows (includes components to remove interferences) | 100/pkg | 4456369 |
| Nitrate Ionic Strength Adjustor Buffer Solution (includes components to remove interferences) | 500 mL | 2488349 |
| Nitrate Standard Solution, 1 mg/L NO ₃ —N | 500 mL | 204649 |
| Nitrate Standard Solution, 10 mg/L NO ₃ —N | 500 mL | 30749 |
| Nitrate Standard Solution, 100 mg/L NO ₃ —N | 500 mL | 194749 |
| Nitrate Standard Solution, 1000 mg/L NO ₃ —N | 500 mL | 1279249 |
| Wash bottle, polyethylene, 500 mL | 1 | 62011 |
| Disposable wipes, 11 x 22 cm | 280/pkg | 2097000 |



Nitraver Colorimetric vs Nitrate Probe

➤ Nitrate Probe

- Calibration standards don't encompass low range.
- Results tend to be erratic.

► Nitraver

Pollution prevention and waste management

Reacted samples contain cadmium and must be disposed of as a hazardous waste. Dispose of reacted solutions according to local, state and federal regulations.





Spectrophotometers (DR 3900)






Spectrophotometers (DR 3900)





Spectrophotometers (DR 3900)





APPARATUS VARIANCE

- Separate Items for Each Analyte
 - Reagents
 - Sample Cells
 - CellOrientation
 - Procedures

| Table 1 | Instrument-specific information |
|---------|---------------------------------|
|---------|---------------------------------|

| Instrument | Sample cell orientation | Sample cell |
|------------|--|------------------|
| DR 6000 | The fill line is to the right. | 2495402 10 mL |
| DR 3800 | | |
| DR 2800 | | |
| DR 2700 | | |
| DR 1900 | | |
| DR 5000 | The fill line is toward the user. | |
| DR 3900 | | |
| DR 900 | The orientation mark is toward the user. | 2401906 |
| | | - 10 m. |





SOUTHERN ILLINOIS UNIVERSITY

EDWARDSVILLE


Turbidimeters

2. The scattered light method





Also known as the **nephelometric method**, this measures the intensity of scattered light at 90°. This method is perfect for measuring samples with low turbidity, and both FNU and NTU can be used.



2100P Turbidimeters

1.4.4 Calibration

The 2100P Portable Turbidimeter is calibrated with Formazin Primary Standard at the factory. However, the instrument should be calibrated upon receipt for best results. Hach recommends recalibration with

16

SECTION 1, continued

formazin once every three months, or more often as experience dictates. The Gelex Secondary Standards supplied with the instrument (included with 4650000 only) are labelled with general ranges for application, but must be assigned values before use from formazin calibration. See Section 3.6 on page 37 for calibration instructions.



SOUTHERN ILLINOIS UNIVERSITY EDWARDSVILLE

Turbidimeters





How accurate is your lab turbidimeter? And are your results repeatable?

A single detection point at 90° is prone to inaccuracy and repeatability issues.

- Sample cell needs to be indexed to get repeatable results using the same vial position
- Sample cell needs a thin layer of silicone oil to avoid measurement errors from scratches



Experience more accurate and repeatable results with innovative technology





- No need for indexing or application of silicone oil
- Effect of surface and position of the vial is minimized as each measurement collects data from the full 360 radii of the vial

SOUTHERN ILLINOIS UNIVERSITY EDWARDSVILLE



Turbidimeters







Benchtop Turbidimeters







Benchtop Turbidimeters



SOUTHERN ILLINOIS UNIVERSITY EDWARDSVILLE



Online Turbidimeters









Online Turbidimeters (TU5300)

CAL CURVE²

Selects the type of standard and the calibration curve (range).

STABLCAL 0-40 FNU (default)—1-point calibration (20 FNU) with StablCal.

STABLCAL 0-1000 FNU-2-point calibration (20 FNU and 600 FNU) with StablCal.

FORMAZIN 0-40 FNU-2-point calibration (20 FNU and dilution water) with Formazin.

FORMAZIN 0-1000 FNU—3-point calibration (20 FNU and 600 FNU and dilution water) with Formazin.

CUSTOM—2- to 6-point calibration (0.02 to 1000 FNU) with StablCal or Formazin. The user selects the number of calibration points and the value of each calibration point.

STABLCAL 0-40 NTU (or 0-40 FNU) (default)—1-point calibration (20 NTU or 20 FNU) with StablCal.

STABLCAL 0-700 NTU (or 0-1000 FNU)—2-point calibration (20 NTU and 600 NTU or 20 FNU and 600 FNU) with StablCal.

FORMAZIN 0-40 NTU (or 0-40 FNU)—2-point calibration (20 NTU and dilution water or 20 FNU and dilution water) with Formazin.

FORMAZIN 0-700 NTU (or 0-1000 FNU)—3-point calibration (20 NTU and 600 NTU and dilution water or 20 FNU and 600 FNU and dilution water) with Formazin.

CUSTOM—2- to 6-point calibration (0.02 to 700 NTU or 0.02 to 1000 FNU) with StablCal or Formazin. The user selects the number of calibration points and the value of each calibration point.



Online Turbidimeters (TU5300)

CAL REMINDER

Sets the time interval between calibrations. The controller will show a reminder when a calibration is due. When a calibration is done, the calibration time is set to zero. Options: OFF(default), 1 day, 7 days, 30 days or 90 days.



QUESTIONS?

Personal Contact

MATTHEW MAAS

618-650-2214

mmaas@siue.edu

Center Contact

ERTC OFFICE

618-650-2030

ertcinfo@siue.edu



SOUTHERN ILLINOIS UNIVERSITY

EDWARDSVILLE